

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.135 OF 2021

PORT OF CORNER INLET AND PORT ALBERT

CORNER INLET

MAJOR BUOY EXCHANGE PROGRAM 2021 COMPLETED

DATE: 21st May 2021

PREVIOUS NOTICE: Notice to Mariners No.131(P) of 2021 is referred.

DETAILS: Mariners are advised that the exchange of Major Navigation Buoyage in the Port of Corner Inlet has been completed. Details of the buoys exchanged follows:

Bennison Spit East Cardinal Mark Buoy (Q(3)10s.3m.4M) has been relocated approximately 200m East to a new position,

- Lat. 38° 46.003' S
- Lon. 146° 26.374' E Datum WGS84

Corner Inlet No.5 Starboard Lateral Mark Buoy (Fl.G.3s.4m.4M) has been relocated approximately 50m West to a new position,

- Lat. 38° 50.593' S
- Lon. 146° 33.408' E Datum WGS84

Corner Inlet No.4 Port Lateral Mark Buoy (Fl.R.2s.4m.4M) has been exchanged in the same position,

- Lat. 38° 48.071' S
- Lon. 146° 30.059' E Datum WGS84

Corner Inlet No.6 Port Lateral Mark Buoy (Fl.R.4s.4m.4M) has been exchanged in the same position,

- Lat. 38° 47.050' S
- Lon. 146° 28.810' E Datum WGS84

NOTICE TO MARINERS

GIPPSLAND PORTS



CHARTS Chart Aus.181 & ENC A439146
AFFECTED:

PUBLICATIONS Admiralty Sailing Directions – Australian Pilot Vol II NP14
AFFECTED: Gippsland Ports Waterways online website available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER No further notice will be issued.
NOTICE:

CAPT. BEVIS HAYWARD
HARBOUR MASTER