

# LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation warning is published for general information.

**AUSTRALIA - VICTORIA**

**No.21 OF 2016**

**PORT OF GIPPSLAND LAKES**

**LOCH SPORT – TOWN PRECINCT**

**No Boating Zone Buoys Replaced by Lit Pile Beacons**

**DATE:** 7<sup>th</sup> September 2016 – effective Immediately

**DETAILS:** Mariners are advised that the two (2) Loch Sport – No Boating Zones previously marked by red unlit buoys have been replaced by lit yellow special mark pile beacons.

The Loch Sport Northeastern No Boating Zone has been marked by two (2) special mark beacons with the top mark Saint Andrews Cross and light characteristics of Fl.Y 2s in the following positions;

No1

Lat. 38° 02.180' S

Lon. 147° 35.212' E

No2

Lat. 38° 02.327' S

Lon. 147° 35.097' E Datum WGS84

The Loch Sport Southwestern No Boating Zone has been marked by two (2) special mark beacons with the top mark Saint Andrews Cross and light characteristics of Fl.Y 2s in the following positions;

No1

Lat. 38° 02.805' S

Lon. 147° 34.624' E

No2

Lat. 38° 02.930' S

Lon. 147° 34.501' E Datum WGS84.

Mariners are advised that boating activities are prohibited within the zones and to take notice of the changed characteristics of the two (2) zones and their associated aids to navigation

**PUBLICATIONS AFFECTED:** Gippsland Lakes Boating Guide, electronic version available on the Gippsland Ports website at [www.gippslandports.vic.gov.au](http://www.gippslandports.vic.gov.au)

**FURTHER NOTICE:** No further Notice will be issued

**BEVIS HAYWARD  
HARBOUR MASTER**