

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA

No.9 OF 2017

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL

ALTERATION TO BUOYAGE

DATE: 9th August 2017

DETAILS: Mariners are advised that the No.3 Starboard hand buoy in the Anderson Inlet Channel has been relocated due to changed channel configuration.

The No.3 buoy has been re-established in the following position:

Lat. 38° 38.272' S. Long. 145° 43.817' E. Datum – WGS84

Mariners are reminded of the dynamic nature of the seabed at this inner entrance location and that the channel, although marked, may not carry water at certain stages of the tide cycle.

Mariners should not attempt to navigate the inner entrance channel or ocean access bar without sound local knowledge and a thorough understanding of environmental conditions and tide cycles. Notice to Mariners No 221 of 2016 refers.

PUBLICATIONS AFFECTED: Anderson Inlet Boating Guide – Electronic Version on Waterways Online available on the Gippsland Ports website at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: This Notice is self-cancelling.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**