

LOCAL NAVIGATION WARNING

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA

No.11 OF 2017

PORT OF GIPPSLAND LAKES

BANCROFT BAY – MOSQUITO POINT

AIDS TO NAVIGATION ESTABLISHED

DATE: 22nd August 2017 – Effective immediately

DETAILS: To promote vessel and waterway user safety, Mariners are advised that Gippsland Ports has established four (4) yellow “**5 knot light buoys**” to mark the 100m boundary of the 5 knot speed restriction zone along the shoreline adjacent to Mosquito Point, Bancroft Bay.

To the South East of Mosquito Point two (2) yellow “**5 knot light buoys**” have been established as follows;

1. Lat. 37° 53.402' S. Lon. 147° 52.193' E. (Fl.Y.2.5s) (Datum – WGS84)
2. Lat. 37° 53.550' S. Lon. 147° 52.387' E. (Fl.Y.2.5s) (Datum – WGS84)

To the South West of Mosquito Point two (2) yellow “**5 knot light buoys**” have been established as follows;

1. Lat. 37° 53.449' S. Lon. 147° 51.808' E. (Fl.Y.2.5s) (Datum – WGS84)
2. Lat. 37° 53.637' S. Lon. 147° 51.701' E. (Fl.Y.2.5s) (Datum – WGS84)

Gippsland Ports shall be withdrawing the Mosquito Point light beacon (Fl.R.4s) from service as this aid to navigation has been replaced by a port hand lateral mark light buoy (LNW No 10 of 2017 refers). A further notice shall be issued on the completion of these works.

PUBLICATIONS AFFECTED: Gippsland Lakes Boating Guide “Waterways Online” available on the Gippsland Ports website at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: A further Notice shall be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**