

LOCAL NAVIGATION WARNING

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA

No.12 OF 2017

PORT OF GIPPSLAND LAKES

BANCROFT BAY

MOSQUITO POINT LIGHT BEACON WITHDRAWN FROM SERVICE

DATE: 30th August 2017 – Effective immediately

PREVIOUS NOTICE: LNW No 10 & 11 of 2017 are referred.

DETAILS: Mariners are advised that the Mosquito Point Light Beacon (Fl. R.4s) formally in position;
Lat. 37° 53.339' South
Lon. 147° 51.928' East
has been withdrawn from service. This beacon has been replaced by a port hand lateral mark buoy (Fl.R.4s) established on 21st August 2017, LNW no 10 of 2017 refers.

Further information can be obtained from Gippsland Ports Notice to Mariners Website at;
<https://www.gippslandports.vic.gov.au/notice-alerts/notice-to-mariners-and-warnings/>

PUBLICATIONS AFFECTED: Gippsland Lakes Boating Guide “Waterways Online” available on the Gippsland Ports website at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further Notice shall be issued.

CAPT. BEVIS HAYWARD
HARBOUR MASTER