

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA

No.14 OF 2017

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL

ALTERATION TO BUOYAGE

DATE: 28th November 2017

PREVIOUS NOTICE: LNW No 28(T) of 2016 is referred and cancelled

DETAILS: Mariners are advised of alterations to navigation buoyage in the vicinity of Inverloch Jetty and the inner entrance of the Anderson Inlet Channel.

The No.2 Port Hand lateral mark buoy has been returned to service.
The No 6A Port Hand Lateral Mark buoy has been withdrawn from service

Alteration to buoy numbering and positions are :

No.2 Port Hand Buoy : Lat. 38° 38.477' S. Long. 145° 43.433' E.
No.3 Starboard Hand Buoy : Lat. 38° 38.255' S. Long. 145° 43.826' E.
No.4 Port Hand Buoy : Lat. 38° 38.239' S. Long. 145° 44.098' E.

Datum : WGS84

Mariners are reminded of the dynamic nature of the seabed in this vicinity and that the channel, although marked, may be impacted by shoaling.

PUBLICATIONS AFFECTED: Anderson Inlet Boating Guide – available on the Gippsland Ports Waterways Online website at <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**