

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

LNN No.2 OF 2018

PORT OF GIPPSLAND LAKES

AIDS TO NAVIGATION ESTABLISHED

AIDS TO NAVIGATION LIT

DATE: Monday 22nd January 2018

DETAILS: Mariners are advised that Gippsland Ports have established or lit Aids to Navigation in the Gippsland Lakes as follows;

1. Butler Point (Entrance to Newlands Arm) - a Port Hand Lateral Mark beacon (Fl.R.2s) has been established in position;

Lat. 37° 55.344' South

Lon. 147° 42.778' East

Datum WGS84

2. Bluff Head Point - Starboard Hand Lateral Mark beacon (Fl.G.4s) has been established in position;

Lat. 37° 56.135' South

Lon. 147° 42.603' East

Datum WGS84

3. Wollaston Bay – the existing Port Hand Lateral Mark beacon has been lit (Fl.R.4s) in position;

Lat. 37° 55.275' South

Lon. 147° 46.936' East

Datum WGS84

4. Paynesville Canal – three (3) unlit 5 knot speed restriction buoys have been established in the following positions

(i) Lat. 37° 54.223' South

Lon. 147° 43.404' East

(ii) Lat. 37° 54.686' South

Lon. 147° 43.457' East

(iii) Lat. 37° 54.852' South

Lon. 147° 43.495' East

Datum WGS84

5. Approaches to the McLennan Strait – three (3) existing Port Hand Lateral Mark beacons have been lit and synchronised as follows;

(i) Beacon Number 4 (Fl.R.3s) in position;

Lat. 38° 02.950' South

Lon. 147° 28.843' East

Datum WGS84

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



(ii) Beacon Number 8 (Fl.R.3s) in position
Lat 38° 03.039' South
Lon. 147° 28.253' East Datum WGS84

(iii) Beacon Number 12 (Fl.R3s) in position;
Lat. 38° 03.116' South
Lon 147° 28.241' East Datum WGS84

Further Information is available from Gippsland Ports on 0427610025

PUBLICATIONS: Gippsland Lakes Boating Guide – electronic version – available at
AFFECTED: www.gippslandports.vic.gov.au/boating/waterways-online

FURTHER NOTICE: No further notice shall be issued

CAPT. BEVIS HAYWARD
HARBOUR MASTER