

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

No.11(T) OF 2018

PORT OF ANDERSON INLET

AIDS TO NAVIGATION TEMPORARILY WITHDRAWN FROM SERVICE

DATE: Thursday 2nd August 2018

DETAILS: Mariners are advised that due to significant changes in channel configuration the Anderson Inlet #1 Starboard Lateral Mark Buoy formerly in position;

Lat. 38° 38.474' S

Lon. 145° 43.484' E

Datum WGS 84

Has temporarily been withdrawn from service; and

Anderson Inlet #2 Port Lateral Mark Buoy formerly in position;

Lat. 38° 38.477' S

Lon. 145° 43.433' E

Datum WGS84

Has also been temporarily withdrawn from service.

Gippsland Ports shall re-establish the #1 & #2 Buoys when the channel configuration stabilises and provides an acceptable fairway to mark.

Further Information is available from Gippsland Ports on 0427610025

PUBLICATIONS: Gippsland Ports Waterways Online – Anderson Inlet available at;

AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: A further Notice will be issued

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**