

# NOTICE TO MARINERS

**GIPPSLAND PORTS**



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No.291(T) OF 2019**

**PORT OF GIPPSLAND LAKES**

**NORTH ARM - SHOALING NEAR THE ENTRANCE**

**STARBOARD LATERAL BUOY ESTABLISHED**

**DATE:** 27<sup>th</sup> November 2019

**DETAILS:** Mariners are advised that shoaling has occurred on the Highway Bridge side of the entrance to North Arm. A (temporary) Starboard Hand Lateral Buoy (FL.G.2s), has been established to mark the Northern edge of the shoal which extends approximately 50 metres into the North Arm channel from Bullock Island. The buoy has been established in position;  
Lat. 37° 53.008' S  
Lon. 147° 58.070' E Datum WGS84

Mariners are advised to take extra precaution when transiting through the North Arm Channel near the entrance.

A further notice shall be issued as soon as dredging works are completed and depths are restored.

Further Information can be obtained by contacting Gippsland Ports on 0351 500 500 or visit the Gippsland Ports Website at;  
[www.gippslandports.vic.gov.au](http://www.gippslandports.vic.gov.au)

**CHART**  
**AFFECTED:** Chart Aus. 182

**PUBLICATIONS**  
**AFFECTED:** Waterways Online at Gippsland Ports website  
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER**  
**NOTICE:** A further Notice will be issued

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**