

# Local Navigation Notice

**GIPPSLAND PORTS**



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No. 02 OF 2020**

**PORT OF GIPPSLAND LAKES – LAKE VICTORIA**

**APPROACHES TO LOCH SPORT**

**BEACON ESTABLISHED – LIGHT ESTABLISHED**

**DATE:** 17<sup>th</sup> February 2020

**DETAILS:** Mariners are advised that Loch Sport Buoy No. 3 (Fl.G.5s) has been replaced by a Starboard Lateral Mark beacon in position;  
Lat. 38° 02.562' S  
Lon. 147° 34.934' E Datum WGS84  
The light flash character remains unchanged.

Loch Sport No. 4 Port Lateral Mark beacon, in position;  
Lat. 38° 02.555' S  
Lon. 147° 34.959' E Datum WGS84  
has been lit with the Flash Character Fl.R.4s.

Further information can be obtained from Gippsland Ports Harbour Master on Ph.0427 610 025.

**PUBLICATIONS** Waterways Online at Gippsland Ports website  
**AFFECTED:** <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER** No further Notice will be issued.  
**NOTICE:**

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**