

LOCAL NAVIGATION NOTICE



GIPPSLAND PORTS

The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

No.9 OF 2020

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL LATERAL MARK BUOYS

TEMPORARILY WITHDRAWN FROM SERVICE

DATE: 27th November 2020

PREVIOUS NOTICE: Local Navigation Notice No.3 of 2020 is referred and cancelled.

DETAILS: Mariners are advised that due to the dynamic nature of the Anderson Inlet waterway, near the entrance and inner channels, and following a recent bathymetric survey, it has been identified that sandy shoals have formed upstream of the Inverloch Boat Ramp. Channel configurations are inconsistent for the time being which has made it necessary for Gippsland Ports to temporarily withdraw three aids to navigation immediately upstream from the Boat Ramp. The three buoys that have been temporarily withdrawn are;

Starboard Lateral mark Buoy No 3.

Former Position:

Lat. 38° 38.224' S

Lon. 145° 44.142' E

Port Lateral mark Buoy No 4.

Former Position:

Lat. 38° 38.222' S

Lon. 145° 44.102' E

Port Lateral mark buoy No.6

Former position:

Lat. 38° 38.413' S

Lon. 145° 44.212' E

Datum WGS84

Due to the constant changing configuration of the Anderson Inlet channel Mariners are advised to check the Gippsland Ports Waterways Online website for the current positions of navigation buoys.

LOCAL NAVIGATION NOTICE



GIPPSLAND PORTS

Mariners are also advised that due to the dynamic nature of the Anderson Inlet waterway, channel configurations may change over short periods of time.

Further Information is available from Gippsland Ports Harbour Master on 0427 610 025.

PUBLICATIONS Gippsland Ports Waterways Online available at;
AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER A further Notice shall be issued.
NOTICE:

CAPTAIN BEVIS HAYWARD
HARBOUR MASTER