

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.222 OF 2021

PORT OF CORNER INLET AND PORT ALBERT

CORNER INLET – MAIN CHANNEL

CHANGE TO LIGHT BUOY FLASH CHARACTERS

LIGHTS SYNCHRONIZED.

DATE: 13th July 2021

DETAILS: Mariners are advised that the light Flash Character of Corner Inlet Main Channel Light Buoys #2, #4 and #6 have been changed as follows:

- Corner Inlet No.2 Port Lateral Mark Buoy Fl.R.4s. 3m 4M
- Corner Inlet No.4 Port Lateral Mark Buoy Fl.R.4s. 3m 4M
- Corner Inlet No.6 Port Lateral Mark Buoy Fl.R.4s. 3m 4M

There has been no change to the position of the Main Channel Light Buoys.

The Corner Inlet Main Channel lights numbered 2, 4 and 6 have been synchronized with the flash rate of 0.5s ON 3.5s OFF.

**CHARTS
AFFECTED:** Chart Aus.181 & ENC AU439146

**PUBLICATIONS
AFFECTED:** Admiralty Sailing Directions – Australian Pilot Vol II NP14
Gippsland Ports Waterways online website available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER
NOTICE:** No further notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**