

# LOCAL NAVIGATION WARNING

GIPPSLAND PORTS



The following navigation warning is published for general information.

**AUSTRALIA - VICTORIA**

**LNW No.11 OF 2021**

**PORT OF GIPPSLAND LAKES**

**THE NARROWS**

**No.5 BEACON DAMAGED – TEMPORARY LIGHT ESTABLISHED**

**DATE:** Monday 1<sup>st</sup> November 2021

**DETAILS:** Mariners are advised that the Starboard Lateral Mark No.5 Beacon in The Narrows at Lakes Entrance has been damaged by vessel strike. The position of the No.5 Beacon is;  
Lat. 37° 52.919' S  
Lon. 147° 57.030' E Datum GDA94

The beacon has a substantial lean upstream and a temporary light (Fl.G.4s) has been re-established to the damaged beacon, pending remedial works to replace. The starboard top mark remains missing from the pile top.

Mariners are advised to take extra precaution when transiting the Narrows channel near No.5 Beacon.

Mariners are invited to contact the Harbour Master on 0427 610 025 should they wish to discuss Port Operations. Mariners are also invited to visit the Gippsland Ports website at;  
[www.gippslandports.vic.gov.au](http://www.gippslandports.vic.gov.au)

**FURTHER  
NOTICE:**

A further notice will be issued when the beacon has been replaced.

**CAPT. BEVIS HAYWARD  
HARBOUR MASTER**