



NOTICE TO MARINERS

GIPPSLAND PORTS

The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

NOTICE TO MARINERS No.087 OF 2024

PORT OF CORNER INLET AND PORT ALBERT

PORT WELSHPOOL HARBOUR

STARBOARD LATERAL BUOYS No.25 AND No.25A

HAVE BEEN DAMAGED AND ARE UNLIT

DATE: Friday 23rd February 2024

PREVIOUS NOTICE: No previous notice issued.

DETAILS: Mariners are advised that due to a Marine Incident Port Welshpool Harbour Starboard Lateral Mark Buoys No.25 (Q.G) and No.25A (Q.G) guarding the shoals South East of the Port Welshpool RoRo facility have been damaged and are unlit. The buoys remain afloat approximately in position, but their current position has not been accurately assessed. See attached Map with the two buoys circled in red.

The buoys will require exchange. A temporary Lit Starboard Lateral Mark Buoy will be established as soon as environmentally possible.

Mariners are requested to navigate with extra precaution when approaching or departing Port Welshpool Harbour especially at night.

Mariners are advised to arrive and depart during higher tides to mitigate possible groundings on the shoal.

Further details can be obtained from Gippsland Ports Harbour Master on 0427 610 025

CHARTS AFFECTED:

Chart Aus.181 – ENC AU439146

NOTICE TO MARINERS



GIPPSLAND PORTS

PUBLICATIONS

AFFECTED: Gippsland Ports Waterways Online available at;
[Gippsland Ports - Waterways Online v2 \(arcgis.com\)](http://Gippsland Ports - Waterways Online v2 (arcgis.com))

FURTHER

NOTICE: A further Notice will be issued.

CAPT. BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS