NOTICE TO MARINERS

GIPPSLAND PORTS

The following Notice to Mariners is published for general information.

AUSTRALIA

VICTORIA

NO.020 OF 2017

PORT OF CORNER INLET & PORT ALBERT

PORT ALBERT CHANNEL

FAIRWAY BUOY LIGHT REINSTATED TO NORMAL

NO.1 BEACON LIGHT REINSTATED TO NORMAL

DATE: 16th January 2017 – Effective Immediately

PREVIOUS NOTICE: Notice to Mariners No 005(T) of 2017 is referred and cancelled
Notice to Mariners No 006(T) of 2017 is referred and cancelled

DETAILS: Mariners are advised that the Port Albert Entrance Fairway Buoy Light, LFl.10s has been reinstated to normal
Charted Position:
Lat. 38° 43.974' S
Lon. 146° 42.675' E Datum WGS84

Mariners are advised that the Port Albert Channel No.1 Beacon Light, Fl.G.4s, has been reinstated to normal.
Charted Position :
Lat. 38° 42.995' S
Lon. 146° 40.999' E Datum WGS84

Further information can be obtained by contacting Gippsland Ports Port Welshpool Office on 0356881303.

CHART AFFECTED: Aus.181, AUS 182

PUBLICATIONS AFFECTED: NP14 Australia Pilot Vol 2, Vol K List of Lights.
Gippsland Ports Online Boating Guide electronic version available at www.gippslandports.vic.gov.au

FURTHER NOTICE: No further Notice shall be issued

CAPT. BEVIS HAYWARD
HARBOUR MASTER