

# NOTICE TO MARINERS

## GIPPSLAND PORTS



The following navigation warning is published for general information

**AUSTRALIA - VICTORIA**

**No.136 OF 2021**

**PORT OF CORNER INLET AND PORT ALBERT**

**APPROACH TO PORT ALBERT ENTRANCE**

**BUOY EXCHANGE PROGRAM 2021 COMPLETED**

**DATE:** 21<sup>st</sup> May 2021

**PREVIOUS NOTICE:** Notice to Mariners No.131(P) of 2021 is referred and cancelled

**DETAILS:** Mariners are advised that the exchange of Navigation Buoyage in the approach to Port Albert has been completed. Details of the Buoys exchanged follows:

Port Albert Fairway Buoy (LFl.10s)

- Lat. 38° 45.185' S
- Lon. 146° 42.401' E Datum WGS84

Port Albert Outer Green Buoy (Fl.G.3s)

- Lat. 38° 45.156' S
- Lon. 146° 41.415' E Datum WGS84

There has been no change to the position or the flash character for these two buoys.

**CHARTS AFFECTED:** Chart Aus.181 & ENC AU439146

**PUBLICATIONS AFFECTED:** Admiralty Sailing Directions – Australian Pilot Vol II NP14  
Gippsland Ports Waterways online website available at;  
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER NOTICE:** No further notice will be issued.

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**