## **NOTICE TO MARINERS**

## **GIPPSLAND PORTS**



The following navigation warning is published for general information

## Australia - Victoria No.147 of 2021

## PORT OF GIPPSLAND LAKES – LAKES ENTRANCE REEVE CHANNEL NO.6 PORT LATERAL MARK BUOY RELOCATED

**DATE:** 28<sup>th</sup> May 2021.

PREVIOUS NOTICE: Notice to Mariners No.108 of 2021 is referred and

cancelled.

**DETAILS:** Mariners are advised that Reeve Channel No.6 Port

Lateral Mark Buoy (Fl.R.3s) has been relocated to new

position:

Lat. 37° 52.839' S

Lon. 147° 57.614' E Datum WGS84

Further information can be obtained from Gippsland

Ports Harbour Master at:

bevish@gippslandports.vic.gov.au

**ENC AFFECTED:** Au5LEN01

**Publications Affected:** Gippsland Ports Waterways Online available at;

https://www.gippslandports.vic.gov.au/boating/waterw

ays-online/

FURTHER No further Notice shall be issued

NOTICE:

CAPT. BEVIS HAYWARD HARBOUR MASTER