

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

DATE:23/04/2012

AUSTRALIA - VICTORIA

No. 084-2012

PORT OF ANDERSON INLET

ANDERSON INLET ENTRANCE

ALTERATION TO NAVIGATION

DATE: With Immediate Effect.

DETAILS: Mariners are advised that the Fairway Light buoy at the Anderson Inlet entrance has been relocated to the following position:

38° 39.467qS
145° 43.483qE (WGS84)

The light has the following flash characteristic:

LFI 10s 2m 2M

**CHARTS
AFFECTED:** AUS 801

**PUBLICATIONS
AFFECTED:** NP14, NP83 (Vol.K)

**FURTHER
NOTICE:** This notice is self cancelling and no further notice will be issued.

**CAPT. TIM HUNGERFORD-MORGAN
HARBOUR MASTER**