

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA

No.19 OF 2016

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL

NAVIGATION BUOYS ESTABLISHED

DATE: 15th August 2016 – effective Immediately

DETAILS: Mariners are advised that two additional Port Hand navigation buoys have been established in the Anderson Inlet Channel, between the Inverloch Jetty and Point Smythe. The Anderson Inlet Channel has migrated further to the east due to growth of a large sand bank, projecting into the Anderson Inlet waterway.

The unlit buoy positions and numbering are :

1. No.6A
Lat. 38° 38.292' S. , Long. 145° 44.013' E.
2. No.8A
Lat. 38° 38.655' S. , Long. 145° 44.235' E.

Datum – WGS84

Mariners are advised to navigate the port waters with caution as the channels and shoals continue to undergo change.

PUBLICATIONS Anderson Inlet Boating Guide, electronic version available on the
AFFECTED: Gippsland Ports Waterways Online at www.gippslandports.vic.gov.au

FURTHER No further Notice will be issued
NOTICE:

BEVIS HAYWARD
HARBOUR MASTER