

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No. 182 OF 2017

PORT OF MALLACOOTA

BASTION POINT AND GOODWIN SANDS

NAVIGATION AID LIGHTING RETURNED TO SERVICE

DATE: 29th June 2017

DETAILS: Mariners are advised that the unreliable navigation aid lights at Bastion Point Boat Ramp Channel and the Goodwin Sands, previously referred, have been returned to service.

Lights affected were :

Bastion Point Boat Ramp Channel

1. No.1 Light Beacon , (Fl.G 3s)
Lat 37° 34.241' S. Long. 149° 45.884' E.
2. No.2 Light Beacon , (Fl.R 2s)
Lat. 37° 34.251' S. Long. 149° 45.901' E.

Goodwin Sands

1. No.1 Light Beacon , (Fl.G 3s)
Lat. 37° 31.769' S. Long. 149° 45.739' E.
2. No.3 Light Beacon , (Fl.G 4s)
Lat. 37° 31.557' S. Long. 149° 45.716' E.
3. No.5 Light Beacon , (Fl.G 5s)
Lat. 37° 31.365' S. , Long. 149° 46.239' E.

PREVIOUS NOTICE NTM 181 (T) of 2017 refers and is cancelled.

FURTHER NOTICE: No further Notice will be issued.

ALAN SMITH
ACTING HARBOUR MASTER