

LOCAL NAVIGATION WARNING

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA

No.18 OF 2017

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL

BUOYS RETURNED TO CHARTED POSITIONS

DATE: 19th December 2017

PREVIOUS NOTICE: LNW 17(T) of 2017 refers and is cancelled.

DETAILS: Mariners are advised that the Number 8A , No.8 and No.10 Buoys have been returned to their charted Positions.

Charted Positions are :

No.8A Port Hand Buoy :	Lat. 38° 38.655' S.	Long. 145° 44.235' E.
No.8 Port Hand Buoy :	Lat. 38° 38.675' S.	Long. 145° 44.387' E.
No.10 Port Hand Buoy :	Lat. 38° 38.601' S.	Long. 145° 44.630' E.

Datum : WGS84

PUBLICATIONS AFFECTED: Anderson Inlet Boating Guide – available on the Gippsland Ports Waterways Online website at <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further notice will be issued.

ALAN SMITH
ACTING HARBOUR MASTER