

LOCAL NAVIGATION WARNING

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA - VICTORIA
No.4 of 2018
PORT OF GIPPSLAND LAKES
TAMBO RIVER APPROACH
AIDS TO NAVIGATION REINSTATED

DATE: Thursday 22nd February 2018

PREVIOUS NOTICE: Local Navigation Warning No 3(T) is referred and cancelled

DETAILS: Mariners are advised that the Tambo River Approach Port lateral mark Buoy number 2B, Fl.R.2s has been reinstated in position;
Lat. 37° 51.745' S
Lon. 147° 47.395' E Datum WGS 84

The Tambo River approach, Starboard lateral mark Buoy Number 1A, Fl.G.2s in position;
Lat. 37° 51.808' S
Lon. 147° 47.386' E Datum WGS 84
has been returned to normal operation.

Further Information is available from Gippsland Ports on 0427610025

PUBLICATIONS: Gippsland Lakes Boating Guide – electronic version – available at
AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further notice shall be issued

CAPT. BEVIS HAYWARD
HARBOUR MASTER