

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No. 215 OF 2018

PORT OF CORNER INLET AND PORT ALBERT

CORNER INLET BUOY EXCHANGE PROGRAM COMPLETED

**PORT ALBERT FAIRWAY AND OUTER GREEN CHANGE TO BUOY
POSITIONS**

DATE: 29th June 2018

PREVIOUS NOTICE: Notice to Mariners No 208(T) is referred and cancelled.

DETAILS: Mariners are advised that the 2018 exchange of navigation buoyage program in Corner Inlet has been completed.

The exchanged buoys in Corner Inlet have been established in the same positions as previously promulgated. Those buoys include; Corner Inlet Main Channel – No.4 (Fl.R.2s) & No.5 (Fl.G.3s). Benison Spit East Cardinal (Q(3).10s). Stockyard Channel – No.2 (Fl.R.4s) & No.4 (Fl.R.8s).

Following a recent survey and due to a significant change in the configuration of the approach at the entrance to Port Albert the Fairway and Outer Green buoys have been re-established in new positions, Details follow;

The Port Albert Fairway buoy (LFl.10s) formerly in position;
Lat. 38° 43.974' S
Lon. 146° 42.675' E – has been withdrawn from service
The new Port Albert Fairway buoy (LFl.10s) has been established in position;
Lat. 38° 45.575' S
Lon. 146° 42.183' E Datum WGS84

The Port Albert Outer Green buoy (Fl.G.3s) formerly in position;
Lat. 38° 44.743' S
Lon. 146° 41.261' E – has been withdrawn from service

NOTICE TO MARINERS

GIPPSLAND PORTS



The new Port Albert Outer Green buoy (Fl.G.3s) has been established in position;

Lat. 38° 45.216' S

Lon. 146° 41.387' E

Datum WGS84

Mariners are advised to take notice of the changed positions of the buoyage at the approach to Port Albert and adjust passage plans accordingly. The latest bathymetric survey for the approach and the Port Albert entrance can be downloaded from the Gippsland Ports website at;

<https://www.gippslandports.vic.gov.au/publications/bathymetric-surveys/>

CHART Chart Aus. 181
AFFECTED:

PUBLICATIONS Admiralty Sailing Directions – Australian Pilot Vol II NP14
AFFECTED:

FURTHER No further Notice shall be issued.
NOTICE:

CAPT. BEVIS HAYWARD
HARBOUR MASTER