

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

No.12 OF 2018

PORT OF ANDERSON INLET

ANDERSON INLET #3 & #8 LATERAL MARK BUOYS RELOCATED

DATE: Monday 3rd September 2018

DETAILS: Mariners are advised that due to significant changes in channel configuration the Anderson Inlet #3 Starboard Lateral Mark Buoy formerly in position;

Lat. 38° 38.255' S

Lon. 145° 43.826' E

Has been relocated to a new position;

Lat. 38° 38.253' S

Lon. 145° 44.048' E

Datum WGS 84

The Anderson Inlet #8 Port Lateral Mark Buoy formerly in position;

Lat. 38° 38.675' S

Lon. 145° 44.387' E

Has been relocated to a new position;

Lat. 38° 38.694' S

Lon. 145° 44.397' E

Datum WGS84

Further Information is available from Gippsland Ports on 0427610025

PUBLICATIONS: Gippsland Ports Waterways Online – Anderson Inlet available at;

AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further notice will be issued.

CAPT. BEVIS HAYWARD
HARBOUR MASTER