

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.017 OF 2020

PORT OF CORNER INLET AND PORT ALBERT

LEWIS CHANNEL AIDS TO NAVIGATION

BEACON EXCHANGE PROGRAM COMPLETED

DATE: 16th January 2020

PREVIOUS NOTICE: NTM No. 156(T) of 2019 is referred and cancelled.
NTM No. 232(T) of 2019 is referred and cancelled.

DETAILS: Mariners are advised that the beacon exchange program commenced in October 2019 has been completed. There is no change to the position or the light characteristic of the beacons.

The beacons exchanged in Lewis Channel are;
Beacon No.2, Port hand lateral beacon (Fl.R 2s)
Beacon No.3 Starboard hand lateral beacon (Fl.G 4s)
Beacon No.9 Starboard hand lateral beacon (Fl.G 4s)

Further information can be obtained by calling the Gippsland Ports Harbour Master on 0427 610 025.

CHARTS AFFECTED Chart Aus. 181 & Aus. 182

PUBLICATIONS AFFECTED: Admiralty Sailing Directions – Australian Pilot Vol II NP14
Gippsland Ports Waterways online website available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

CAPT. BEVIS HAYWARD
HARBOUR MASTER