

LOCAL NAVIGATION NOTICE



GIPPSLAND PORTS

The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

No.3 OF 2020

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL LATERAL MARK BUOYS
REPOSITIONED.

DATE: 31st July 2020

DETAILS: Mariners are advised that due to a change in channel configuration, two unlit lateral marker buoys upstream of the Inverloch boat ramp have been relocated to the following positions:

Starboard Lateral mark Buoy No 3.

Position:

Lat. 38° 38.224' S

Lon. 145° 44.142' E

Port Lateral mark Buoy No 4.

Position:

Lat. 38° 38.222' S

Lon. 145° 44.102' E

Due to constant changing of the Anderson Inlet channel configuration, the channel alignment will be updated from time to time. Mariners are advised to check the Gippsland Ports website for the current positions of all buoys.

Further Information is available from Gippsland Ports Harbour Master on 0427 610 025.

PUBLICATIONS: Gippsland Ports Waterways Online available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further Notice shall be issued.

DAVID ASHWORTH
ASSISTANT HARBOUR MASTER