

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

LNN No.11 OF 2022

PORT OF CORNER INLET AND PORT ALBERT

**BOAT HARBOUR CHANNEL BUOY EXCHANGE AND CHANNEL
REALIGNMENT**

DATE: Monday 14th November 2022

DETAILS: Mariners are advised that, following a recent survey, the Boat Harbour Channel unlit lateral mark buoys near the entrance to Shoal Inlet have been exchanged and positions re-established to align the channel from the Ocean Entrance, upstream as follows;

Boat Harbour Channel Buoy No.1

Lat. 38° 40.535' S

Lon. 146° 49.343' E

Boat Harbour Channel Buoy No.2

Lat. 38° 40.377' S

Lon. 146° 49.034' E

Boat Harbour Channel Buoy No.3

Lat. 38° 40.319' S

Lon. 146° 48.931' E

Boat Harbour Channel Buoy No.4

Lat. 38° 40.463' S

Lon. 146° 48.578' E

Datum WGS84

For further information please contact Gippsland Ports Harbour Master
Ph. 0427 610 025. See attached map overlay for reference.

MAP

AFFECTED

Gippsland Ports Waterways Online Mapping available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER
NOTICE:**

No further notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS**