

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA - VICTORIA

NO.191 OF 2016

PORT OF CORNER INLET & PORT ALBERT

PORT ALBERT ENTRANCE

FAIRWAY LIGHT BUOY RELOCATED

DATE: 30st June 2016 – Effective Immediately

DETAILS: Mariners are advised that the Port Albert Entrance Fairway Light Buoy , (LFI 10s), has been relocated.

New Charted Position :

Lat. 38° 43.974' South
Long. 146° 42.675' East

WGS84 Datum

CHART Aus.181 , Aus 357

AFFECTED:

FURTHER NOTICE: No further notice will be issued.

ALAN SMITH

ACTING HARBOUR MASTER