

LOCAL NAVIGATION NOTICE



GIPPSLAND PORTS

The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

No 7 OF 2019

PORT OF GIPPSLAND LAKES - LAKE VICTORIA

LOCH SPORT APPROACH CHANNEL

AIDS TO NAVIGATION CHANGES FOLLOWING DREDGING OPERATIONS

DATE: 22nd July 2019

DETAILS: Mariners are advised that following the completion of dredging operations the Loch Sport approach channel Starboard hand lateral mark buoy No.1a (Fl.G.5s) formerly in position;
Lat. 38° 02.526' S
Lon. 147° 34.933' E Datum WGS84
Has been withdrawn from Service.

Mariners are also advised that the previously unlit Starboard hand pile beacon No.3 has been replaced by a lit Starboard hand lateral mark buoy No.3 (Fl.G.5s) in the same position;
Lat. 38° 02.562' S
Lon. 147° 34.934' E Datum WGS84

Further Information can be provided by calling the Gippsland Ports Harbour Master on 0427 610 025

PUBLICATIONS: Gippsland Ports Waterways online website available at;
AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further Notice shall be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**