

LOCAL NAVIGATION WARNING



GIPPSLAND PORTS

The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

No.5 OF 2019

PORT OF CORNER INLET AND PORT ALBERT

ENTRANCE TO PELICAN CHANNEL

SOUTH CARDINAL MARK BUOY RELOCATED.

DATE: 17 December 2019

DETAILS: Mariners are advised that due to a change in channel configuration the unlit Pelican Channel South Cardinal Mark buoy (Y.B.) has been relocated to position;
Lat. 38° 39.464' South
Lon. 146° 49.770' East Datum WGS 84

Further Information is available from Gippsland Ports on 03 5688 1303

PUBLICATIONS: Gippsland Lakes Waterways Online – available at
AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER NOTICE: No further Notice shall be issued. .

CAPT. BEVIS HAYWARD
HARBOUR MASTER