

Local Navigation Warning

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No. 04(T) OF 2020

PORT OF MALLACOOTA INLET

BUSHFIRE DAMAGED JETTIES MARKED.

DATE: 16th March 2020

DETAILS: Mariners are advised that several Parks Victoria Jetties have been damaged by the recent severe bushfires. An inspection has now been carried out of the extent of the damage resulting in the following jetties being marked to warn vessel operators.

1/ Gravelly Point Jetty has been marked with a lit no boating buoy (Fl.(2).3s) in position;
Lat. 37° 30.352' S
Lon. 149° 44.513' E Datum WGS 84

2/ Genoa Fire Trail Jetty has been marked with a lit no boating buoy (Fl.(2).3s) in position;
Lat. 37° 29.771' S
Lon. 149° 42.191' E Datum WGS84

3/ Sou'West Arm Jetty has been marked with a lit no boating buoy (Fl.(2).3s) in position;
Lat. 37° 30.476' S
Lon. 149° 41.710' E Datum WGS84

4/ Captain Creek Jetty has been marked with a lit pole (Fl.3s) in position;
Lat. 37° 31.247' S
Lon. 149° 43.100' E Datum WGS84

5/ Kingfisher Point Jetty has been marked with a lit pole (Fl.3s) in position;
Lat. 37° 31.098' S
Lon. 149° 46.517' E Datum WGS84

Local Navigation Warning

GIPPSLAND PORTS



Attached to this Local Navigation Warning is a map of the location of each of these jetties and a photograph of each jetty. Other jetties in the area are not fire affected and remain serviceable and unmarked.

Mariners are advised to stay clear of the damaged jetties until remedial works can be arranged and are reminded that rising flood water may cover some or all the remains of the jetty infrastructure at times.

Further Information can be obtained by contacting Gippsland Ports on 0351 500 500

PUBLICATIONS Waterways Online at Gippsland Ports website
AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER A further Notice will be issued.
NOTICE:

CAPT. BEVIS HAYWARD
HARBOUR MASTER