

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

LNN No.6 OF 2022

SHALLOW INLET

BUOY EXCHANGE PROGRAM COMPLETED

DATE: Thursday 30th June 2022

DETAILS: Mariners are advised that, following a recent survey, the Shallow Inlet unlit lateral mark buoys have been exchanged and positions established from the Ocean Entrance, upstream as follows;

Shallow Inlet #1

Lat. 38° 52.358' S

Lon. 146° 11.775' E

Shallow Inlet #2

Lat. 38° 52.202' S

Lon. 146° 11.672' E

Shallow Inlet #3

Lat. 38° 51.945' S

Lon. 146° 11.639' E

Shallow Inlet #5

Lat. 38° 51.728' S

Lon. 146° 11.493' E

Shallow Inlet #4

Lat. 38° 51.554' S

Lon. 146° 11.350' E

Shallow Inlet #6

Lat. 38° 51.387' S

Lon. 146° 11.267' E

Shallow Inlet #8

Lat. 38° 51.323' S

Lon. 146° 11.144' E

Datum WGS84

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



Shallow Inlet #10
Lat. 38° 51.245' S
Lon. 146° 10.620' E

Shallow Inlet #7
Lat. 38° 51.200' S
Lon. 146° 10.626' E

Shallow Inlet #9
Lat. 38° 50.989' S
Lon. 146° 09.780' E

Shallow Inlet #11
Lat. 38° 50.923' S
Lon. 146° 09.647' E

Shallow Inlet #13
Lat. 38° 50.772' S
Lon. 146° 09.546' E

Datum WGS84

For further information please contact Gippsland Ports Harbour Master
Ph. 0427 610 025

MAP Gippsland Ports Waterways Online Mapping available at;
AFFECTED <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

FURTHER
NOTICE: No further notice will be issued.

CAPT. BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS